


New high limit controller connections

When replacing a High Limit controller that had a contact #7 by the newer controller that does not have the #7 contact.

See below on how to connect the new model. **Please note that wire #9 will be left disconnected**



***** wire #9 needs to be left disconnected*****

Please note that the other contacts are wired the same way as they were on the older High Limit controller version.